ELECTRICL SYSTEM

MAIN SUPPLY AND SERVICE ENTRANCE

- Type: Over head
- Location of the service entrance: From the east side of the building
- Entrance amperes: 100 amps
- Entrance voltage: 240 volts
- Meter: Accessible from outside on the east side
- Conditions:

1- The entrance wires conduit is not sufficient for upgrading the system to 200 amps.

2- The meter covering in the east side is

made of non-conforming material.

3- Keep the perimeter of the meter covering sealed, and also install a top cap

to shed the water away from it.



GROUNDING SYSTEM

• Type: There is a grounding wire connection to the incoming water line and from the panel leaving upward and probably through the ceiling, but the effectiveness of grounding can not be verified.

DISTRIBUTION PANEL AND ITS RATING

- Panel type: Circuit breaker Panel rating 120 Ampere with 240 volts
- Location: In the ground floor Laundry room
- Distribution wire type: Copper
- Conditions:
 - 1- No AFCI was present for bedrooms' outlets due to new standards.
 - 2- No GFCI breaker was present in the panel.
 - 3- It did not have at least 3 feet clearance from the bottom and in front for accessibility.
 - 4- Does not provide enough clearance from sides due to new standards for fire hazards.
 - 5- It did not have directory map for checking the breakers sizes and their connection.
 - 6- If the 2*20 Ampere breakers are serving a specific appliance, they should be connected to each other (which in this case they did not). And due to not presence of a map in the panel this matter could not be checked.
 - 7- There was not room in the panel for future expansion.
 - 8- There was a non-conforming conduit under the base of panel for garage use and continuity of it could not be confirmed.



OVERCURRENT DEVICES

- Type: Circuit breakers
- Conditions: there was co-al circuit breaker in the panel which is for use of both copper and aluminum wires, but the presence of aluminum wire could not be verified.

BRANCH CICUIT WIRING

- Type: Copper
- Conditions:
 - 1- Added wire for lighting switch under the stair did not match the required ampere which would be a fire hazard issue.
 - 2- Added wire for the two installed outlets in the second floor bathroom did not match the required ampere which would be a fire hazard issue.
 - 3- There were out of junction box connection of wires in the attic and under the ceiling of ground floor which could be a fire hazard issue.
 - 4- The wire connection for the ground floor exhaust fan did not match the required ampere and could be a fire hazard issue.
 - 5- There was a loose junction box on the floor with no cap under the stair.
 - 6- There was not appropriate wiring (wiring under the roof joists or over wall covering) for locations such as: Under the ground floor ceiling and in the second floor room (room to the balcony), and a few other places.
 - 7- There were loose wires passing under the beams and joists and under the staircase walls.







OUTLETS AND SWITCHES & LIGHTINGS

• Conditions:

- 1- The only GFCI outlet located on the outside south wall does not have proper cover.
- 2- There is no GFCI outlet in the second floor bath room which is a shock hazard.



3- The outlets close to the kitchen sink were not GFCI type which could be a shock hazard, and the left hand side one is even loose.



- 4- The outlet in the second floor corridor had broken cover which could cause a fire hazard.
- 5- The switch light and junction box used in the ground floor (under the staircase) are nonconforming type.
- 6- Two of the checked outlets had loose wire connections which could be a fire hazard (one in the ground floor close to the room and one in the second floor).





7- The outlets in the ground floor (under the staircase) and in laundry room did not have any cover which could lead to fire hazard issue.





GROUND FAULT CIRCUIT INTERRUPTERS

As mentioned in the panel and outlet section

ARC FAULT CIRCUIT INTERRUPTERS

Type: As mentioned in the panel section

ALARM SYSTEM (SMOKE, CO, AND INTUDER)

- Smoke alarm: I was told that the installed smoke detector did not respond to manual tester, and the fire alarm system in the ground floor needs specialized person due to their type.
- Co alarms: Not applicable
- Intruder alarm: There was an intruder alarm present, but it was not tested.
- *Recommendation*: Install an operable smoke detector on the second floor corridor due to fire and safety concerns.

✤ Recommendation: Check all the aspects of the electrical system for their safety, fire hazard, shock hazard, and their proper operation by a licensed electrical contractor due to mentioned deficiencies. Also improve the accessibility of the panel and confirm the outside installation of the vacuum cleaner.